


TSB-248 Flywheel Resurfacing

The clutch kit supplied for this vehicle is slightly larger than the original unit. It is therefore mandatory that the flywheel friction surface gets resurfaced to the outer edge of the step as illustrated in the image below. The flywheel step needs to be 7.5mm (0.295").



Failure to do so will affect the performance and life of the clutch.

Guality Certified AU1045-QC



IFANING BRANDS

australianclutch.com.au

1800 CLUTCH (258824)